




*slide M4(8-32) screws
 through combined M6/Ø7,4
 mounting/clearance holes to mount the
 unit immediately to M4(8-32) holes, or
 mount the unit directly on any M6 tip